MATERIAL SAFETY DATA SHEET (SUBSTITUTES FOR OSHA FORM 174): May be used to comply with OSHA's Hazard Communication Standard, 29 CFR 1910.1200.

PRODUCT NUMBER: KE-107MUL
DRY MULBERRY AIR & FABRIC FRESHNER

Revision Date: 02/04/2000

Section I

Manufacturer's Name: KINZUA ENVIRONMENTAL, INC.***
Address: 1176 EAST 38TH STREET
CLEVELAND
State: OH Zip Code:44114

Telephone Numbers:
Emergency:
800/ 424-9300
Information:
216/881-4040

HMIS CODES: REACTIVITY: 1 FLAMMABILITY: 1 HEALTH: 1 PERSONAL PROTECT: 1

Section II: HAZARDOUS INGREDIENTS/IDENTITY INFORMATION (All of the ingredients contained in this product are listed on the TSCA inventory.)

Name	Cas No.	OSHA PEL	ACGIH TLV	OTHER LIM	%
ISOPARAFINIC HYDROCARBON	64742-47-8	300 PPM	300 PPM		
L.P.G.	68476-85-7	1000	1000	N/A	

Section III: PHYSICAL/CHEMICAL CHARACTERISTICS

Boiling Point:	165	Specific Gravity (water=1)	0.80
Vapor Pressure(mm Hg)	44	Melting Point:	N/A
Vapor Density(AIR=1)	1	Evaporation Rate:	>1
Solubility in Water:	100%	(Butyl Acetate=1)	

Appearance and Odor: CLEAR SPRAY, MULBERRY ODOR

Section IV: FIRE AND EXPLOSION HAZARD DATA

Flash Point(Method Used):>140F TCC Flammable Limits: LEL:N/A UEL: N/A
Extinguishing Media: CO2,
Special Fire Fighting Procedures: NONE

Unusual Fire and Explosion Hazards: CONTENTS UNDER PRESSURE. EXPOSURE TO TEMPERATURES ABOVE 130 F MAY CAUSE BURSTING. CONTAINS FLAMMABLE PROPELLANT.

Section V: REACTIVITY DATA PRODUCT NUMBER: KE-107MUL

Stability: Unstable: Conditions to avoid:
Stable: X NONE

Incompatability (Materials to Avoid): STRONG OXIDIZERS, ALKALIES, ACIDS

Hazardous Decomposition or Byproducts: NONE KNOWN

Hazardous Polymerization: May Occur: Will Not Occur: X
Conditions to Avoid: NONE

Section VI: HEALTH HAZARD DATA

Routes of Entry: Inhalation: YES Skin: NO Ingestion:NO
Health Hazards(Acute and Chronic):
MAY CAUSE DIZZINESS, HEADACHE AND EYE IRRITATION.

Carcinogenicity: NTP:NO IARC Monographs:NO OSHA Reg:NO
Signs and Symptoms of Exposure: SEE HEALTH HAZARDS ABOVE

Medical Conditions Generally Aggravated by Exposure: NONE KNOWN

Emergency and First Aid Procedures: INHALATION: REMOVE TO FRESH AIR AND SEE PHYSICIAN. EYES: FLUSH WITH WATER AND SEE PHYSICIAN.

Section VII: PRECAUTIONS FOR SAFE HANDLING AND USE

Steps to be Taken in Case Material is Released or Spilled: MOP OR WIPE UP SPILL. DISPOSE OF IN ACCORDANCE WITH FEDERAL, STATE AND LOCAL GUIDELINES.

Waste Disposal Method: WRAP CONTAINER AND PLACE IN TRASH COLLECTION. DO NOT PUNCTURE OR INCINERATE CONTAINER.

Precautions to be Taken in Handling and Storing: STORE IN A COOL DRY AREA. KEEP AWAY FROM HEAT, FLAMES OR SPARKS.

Other Precautions: N/A

Section VIII: CONTROL MEASURES

Respiratory Protection: N/A
Ventilation: Local Exhaust:N/A
Mechanical: N/A Special: N/A
Other: N/A
Protective Gloves:N/A
Eye Protection: N/A
Other Protective Clothing or Equipment: N/A
Work/Hygienic Practices: WASH HANDS AFTER USE